



Consider the grain of the stock when removing material, work the cutting tool with the grain for the best results

## Wood Lathe

Get the approval of a Shop Technician before using this machine.

Mount workpiece firmly between centers, on faceplate or in chuck before turning on machine.

Select appropriate speed before plugging in the machine.

Adjust tool rest to minimal distance from workpiece.

Rotate stock manually before applying power to guarantee proper mounting and toolrest clearance.

Select appropriate turning tool for the task at hand.

ALWAYS hold turning tool firmly with both hands.

ALWAYS tilt turning tool down onto rotating workpiece.

